



PRODUCT RECALLS

Product Safety Information Notice on Can-Am Commander, Maverick Trail and Traxter side by side vehicles

 NOVEMBER 8, 2023

A safety issue has been identified with Can-Am Commander, Maverick Trail and Traxter side by side vehicles.

The risk presented by the product is Injuries. The operator's guide maintenance schedule section contains incorrect information. Lack of proper maintenance of the clutch may lead to clutch failure including fragments to be ejected from the vehicle.

The Trademark is Can-Am. The type/number of models are Commander, Maverick Trail and Traxter series. The model years are 2022 and 2023. The engines affected are HD7 or 700 engines.

There are approximately 5 affected products in the Republic of Ireland.

What to do:

BRP is sending out an updated Maintenance Schedule Booklet containing the revised maintenance schedules.

For more information regarding the product safety information notice please see link to the BRP website [here](#) or contact BRP on +44 20 88 65 04 89.