



PRODUCT RECALLS

Specialized Bicycle Components recalls headlights and taillights

 MAY 11, 2016

Due to a potential fire and burn hazards, Specialized Bicycle Components have initiated a product recall for Specialized Flux and Stix Sport and Comp model bicycle headlights and taillights.

Approximately 200 affected lights were imported and distributed by Specialized (U.K.) Limited in Ireland.

What to do:

Specialized Bicycle Components advice is that, consumers should immediately stop using these recalled headlights and taillights. Return them an authorised Specialized Bicycle retailer for a free repair for Flux model headlights, or a free replacement.



Flux bicycle lights

Consumers who may have any questions in relation to this recall, should contact Specialized Bicycle Component as follows:

Tel: +44 (0)20 8391 3500

Fax: +44 (0)20 8391 3501

Sales: salesuk@specialized.com

Customer Service: customerserviceuk@specialized.com

Marketing: marketinguk@specialized.com