Petzl Distribution SAS Recalls NEWTON, NEWTON FAST, and NEWTON EASYFIT Harnesses – European Versions

MARCH 31, 2025

Petzl Distribution SAS is carrying out a recall on NEWTON, NEWTON FAST and NEWTON EASYFIT Harnesses – European Versions.

The risk reported to the CCPC is injuries. On the affected harnesses, the FAST LT buckle (see image above) is positioned at the chest and is used to fasten the harness. If the harness is attached via the dorsal point and the FAST LT buckle breaks, the harness becomes unfastened. If the user falls or is suspended in the harness, it is possible for them to completely exit the harness and fall to the ground.

The brand is Petzl.

PRODUCT – EUROPEAN VERSION	REFERENCES
NEWTON	C073AA01 and C073AA02
NEWTON FAST	C073CA01 and C073CA02
NEWTON EASYFIT	C073EA01 and C073EA02

There are approximately 18 affected products in the Republic of Ireland.

What to do:

Consumers should stop using the product immediately. To check if your product is affected by this recall, please review the Petzl safety notice . Only certain batches of harnesses manufactured in 2022 are affected by the recall.

If your harness is affected by the recall, please return the harness to Petzl. To do this, contact your local Petzl after-sales service via this contact form.

Petzl is responsible for all shipping costs.