



PRODUCT RECALLS

BMW Motorrad recalls various motorcycles

📅 APRIL 15, 2015

BMW is recalling a number of BMW motorcycles.

The following vehicles are affected:

▪ R 1200 GS (K25)

▪ R 1200 GS Adventure (K25/02)

▪ R 1200 GS (K25/11)

▪ R 1200 GS Adventure (K25/12)

▪ R 1200 GS (K25/31)

▪ R 1200 GS Adventure (K25/32)

▪ HP2 Mega Moto (K25/03)

▪ HP2 Enduro (K25/HP)

▪ R 1200 RT (K26)

▪ R 900 RT (K26)

▪ R 1200 RT (K26/11)

▪ R 900 RT (K26/11)

▪ R 1200 R (K27)

▪ R 1200 R (K27/11)

▪ R 1200 ST (K28)

▪ R 1200 S (K29)

▪ HP2 Sport (K29/HP)

▪ K 1200 S (K40)

▪ K 1200 R Sport (K43/HV)

▪ K 1200 R (K43)

▪ K 1200 GT (K44)

▪ K 1300 S (K40/11)

▪ K 1300 R (K43/11)

▪ K 1300 GT (K44/31)

The manufacture period extends from 04/12/2002 until 05/04/2011. This voluntary recall is being carried out due to a potential problem where cracks may appear in the wheel flange. In the course of use the cracks can propagate and could lead to a fracture of the bolted join. This recall affects approximately 900 vehicles in Ireland.

What to do

Letters will be sent by BMW to owners of the affected vehicles who will be asked to arrange an appointment to have the required repair work completed at their authorised service agent. This will involve the replacement of the aluminium wheel flange with a steel one. Any work carried out as part of this recall will be completed free of charge.