



PRODUCT RECALLS

Jobe Sports International Recalls Jobe Seascooter and Jobe Flux

📅 OCTOBER 30, 2025

Jobe Sports International is carrying out a recall of Jobe Seascooter and Jobe Flux.



The product presents a risk of fire and burns. There is a defect in the internal sealing of certain Jobe Seascooters and Jobe Flux models with specific serial numbers. Water may enter the product, potentially causing a short circuit, smoke, or a burning smell. This may lead to fire and burns.

AFFECTED SEASCOOTER MODELS AND SERIAL NUMBERS

Jobe infinity Seascooter Package:

ESSH022410000001 – ESSH022410000500

ESSH022411000001 – ESSH022411000150

ESSH022503000001 – ESSH022503000440

ESSH022504000001 – ESSH022504000300

ESSH012410000001 – ESSH012410000040

ESSH022410000501 – ESSH022410000530

Jobe infinity Seascooter Pro Package:

ESSH02S2410000001 – ESSH02S2410000600

ESSH02S2412000001 – ESSH02S2412000800

ESSH02S2411000001 – ESSH02S2411000400

ESSH02S2503000001 – ESSH02S2503000460

ESSH02S2504000001 – ESSH02S2504002568

ESSH02S2410000601 – ESSH02S2410000630

Jobe x Jeep Seascooter Package:

ESSH02J2410000531 – ESSH02J2410000680

Jobe x BRABUS Seascooter Package:

ESSH02S2411000001 – ESSH02S2411000200

Jobe Flux Kickboard:

EKB012411000001 – EKB012411000500

EKB012412000001 – EKB012412000250

EKB012504000001 – EKB012504000560

There are approximately 10 affected products in the Republic of Ireland.

What to do:

If you purchased one of these products, please stop use immediately, remove the battery and store the product in a safe, dry place.

[🔗 Check the serial number of your Jobe Seascooter or Jobe Flux](#). Only Jobe Seascooters and Jobe Flux models with the specified serial numbers are affected. All other Jobe Seascooters and

Jobe Flux are safe to use.

If your seascooter is affected, you must fill in the Jobe [warranty form](#) to arrange your free replacement.