



# PRODUCT RECALLS

## Lexus Ireland IS250 recall

 JANUARY 26, 2011

Lexus Ireland is recalling the IS250 Lexus model, due to possible loosening of the fuel pressure sensor causing fuel to leak.

The affected vehicles were produced between 31 August 2007 and 3 February 2009. This recall affects 186 Lexus IS250 vehicles in Ireland.

### What to do:

Lexus Ireland has written to customers detailing the reasons of the recall. This letter advises you to contact your nearest Lexus dealer who will arrange to do the required check and repair, at a mutually convenient time, free of charge.

Lexus owners who may have questions or concerns should contact their local Lexus Dealer or Lexus Ireland Customer Relations for assistance on Freephone 1800 224222, or email [lexuscs@lexus.ie](mailto:lexuscs@lexus.ie).