



PRODUCT RECALLS

Lexus recalls certain CT200h models

 JUNE 30, 2016

Lexus Ireland is carrying out a voluntary recall of certain models of the CT200h. The production period extends from August 2010 to April 2012.

The vehicles involved are equipped with curtain shield air bags (CSA) in the driver and passenger side roof rails that have air bag inflators composed of two chambers welded together. Some inflators could have a small crack in the weld area joining the chambers, which could grow over time, and lead to the separation of the inflator chambers. This has been observed when the vehicle is parked and unoccupied for a period of time. If an inflator separates, the CSA could partially inflate, and, in limited circumstances, one or both sections of the inflator could enter the interior of the vehicle.

There are 353 affected vehicles in Ireland.

What to do

Lexus Ireland will be writing directly to those customers involved in this recall to arrange to have their vehicles checked and re-fitted if necessary. The letter will advise you to contact your nearest Lexus Dealer/Authorised Repairer who will arrange to do the check/repair free of charge. Lexus Ireland can be contacted on: 01 4190222.