



PRODUCT RECALLS

Peugeot 4007 Voluntary Recall

 JUNE 25, 2018

Peugeot Ireland is voluntarily recalling its **4007** model having identified that in certain cases, water entry may lead to total blockage of the windscreen-wiper motor mechanism through internal corrosion, resulting in a risk of restricted visibility for the driver in the event of rain.

AFFECTED UNITS:

143 units were sold in Ireland

Vehicles manufactured between 16/4/2007 and 2/7/2012.

VIN Nos VF3VV4HNNH8U900205 to VF3VV4HK8CU806036;

Recall code Peugeot HYN

What To Do

If you have affected unit return the 4007 to the nearest Peugeot, for attention.

If you have any further queries, please phone Peugeot Customer Services on: [!\[\]\(4b7a79268f6ba26c1471d4232fffa85a_img.jpg\) \(01\) 409 2400](tel:(01)4092400)