



# PRODUCT RECALLS

## Peugeot recalls 308 II

 JUNE 30, 2015

Peugeot Ireland is carrying out a voluntary recall of its 308 II model. It is possible that the front suspension wishbone mounting screws could break. This may cause a difficulty for the driver to control the vehicle's path. There are 797 affected vehicles in Ireland.

### **What to do**

Peugeot Ireland will be writing directly to those owners involved to arrange to have their vehicles fitted with a new component, if necessary. The letter will advise you to contact your nearest Peugeot dealer who will arrange to do the refit free of charge. You can also contact Peugeot Ireland directly on 01-4092400.