



PRODUCT RECALLS

Product Safety Information Notice on Electriq Gas Hobs, Gas Supply Elbow Joint

📅 SEPTEMBER 25, 2023

This is an update of the [Product Safety Information Notice on Electriq Gas Hobs, Gas Supply Elbow Joint - CCPC Consumers](#) posted on 21 July 2023.

A safety issue has been identified with Electriq Gas Hobs, Gas Supply Elbow Joint manufactured after May 2019 and which may be installed in **domestic settings and the leisure market (holiday homes, caravans and boats)**.



IQGH604W




IQGH603S



IQGH75BG



IQGH75WG



IQGH75S



IQGH604B



IQGHVOL

The gas supply elbow joint from the gas hob to the gas supply may fracture, which can cause gas to leak through the fracture. This presents a risk of burns, fire, explosion and poisoning

from inhalation which could pose a risk to health, or even death.

The brand is Electriq. The model numbers are IQGH603S, IQGH604B, IQGH604W, IQGH75BG, IQGH75S, IQGH75WG and IQGHVOL. The batch numbers and barcodes are unknown.

We currently understand the number of the above product units sold to customers in the Republic of Ireland is 850.

What to do:

It is vitally important that consumers do not use their gas hob. The gas hobs above must be urgently inspected and modified. This will be conducted free of charge by a Registered Gas Installer.

If customers are affected by this issue they can contact Electriq at 01 223 9611 or consult the Electriq safety notice [🔗 here](#).

In the meantime, if you smell gas, please contact Gas Networks Ireland immediately on 1800 20 50 50.