



# PRODUCT RECALLS

## Product Safety Information notice on Haier Built In Heat Pump Tumble Dryers

📅 SEPTEMBER 23, 2025

Product safety information notice on Haier Built-in Heat Pump Tumble Dryers. Please note products modified before September 2025 require a second safety modification. Please read 'What to do' for further details.

# Haier

The risk reported to the CCPC is of fire. It is possible for an internal short circuit to occur within the tumble dryer during normal use. This can cause the tumble dryer to ignite, causing a fire.

The affected models are as follows:

DESCRIPTION	BRAND	SKU
HDB4 H7A2TBERX80	HAIER	31900550

The affected product was on sale from 2020 to 2024.

There is approximately 1 affected product in the Republic of Ireland sold via Home Trends Limited.

## What to do:

Customers are strongly advised to stop using the product immediately and contact the manufacturer to arrange for a modification to take place. The product should not be used until the modification has taken place. If the plug is accessible, switch off and unplug the appliance.

Products that were modified before September 2025 require a second modification. Please ensure your machine has received the latest modification.

To find out more about the in-home modification and to check whether your machine is affected, fill out the form [🔗 here](#).