




PRODUCT RECALLS

Product Safety Information Notice on Russell Hobbs gas hobs sold on Amazon

 OCTOBER 27, 2023

A safety issue has been identified with Russell Hobbs Gas Hobs, Gas Supply Elbow Joint sold on Amazon.



RH60GH402B



RH60GH402SS



RH75GH601SS



RH86GH701SS/01



RH75GH602SS



RH75GH602DS



RH86GH702DS



RH60GH403DS



RH86GH702SS/01



RH60GH403SS

The gas supply elbow joint from the gas hob to the gas supply may fracture, which can cause gas to leak through the fracture. This presents a risk of burns, fire, explosion and poisoning from inhalation which could pose a risk to health, or even death.

The brand is Russell Hobbs. The model numbers are listed in the tables below. The batch numbers and barcodes are unknown.

ASIN	MODEL	NUMBER OF AFFECTED PRODUCTS IN THE REPUBLIC OF IRELAND
B017IWHVFE	RH60GH402B	35
B017IWO2GA	RH60GH402SS	33
B01LNQ3RPO	RH75GH601SS	35
B01LNQVML0	RH86GH701SS/01	9
B07BH9XM5S	RH75GH602SS	12

ASIN	MODEL	NUMBER OF AFFECTED PRODUCTS IN THE REPUBLIC OF IRELAND
B07BHB3RLN	RH75GH602DS	41
B07BJNBGR5	RH86GH702DS	11
B07BJNG7VL	RH60GH403DS	18
B07BJNJZD5	RH86GH702SS/01	6

We currently understand the number of the above product units sold through Amazon to customers in the Republic of Ireland is 216.

What to do:

It is vitally important that consumers do not use their gas hob. The gas hobs above must be urgently inspected and modified. This will be conducted free of charge by a Registered Gas Installer.

If customers are affected by this issue they can contact Russell Hobbs at 1 800 938982 or by email on infoROI@mda.russellhobbs.com.

In the meantime, if you smell gas, please contact Gas Networks Ireland immediately on 1800 20 50 50.