



# PRODUCT RECALLS

## SCOTT SPORTS SA recalls SCOTT Speedster Bicycles

📅 MARCH 3, 2023

SCOTT SPORTS SA is carrying out a recall of SCOTT Speedster Bicycles.



Figure 1: Contessa Speedster Gravel 35



Figure 2: Speedster 40



Figure 3: Speedster Gravel 50



Figure 4: Speedster Gravel 40 EQ



Figure 5: Speedster 50

The product presents a risk of injuries as the steering tube in the front fork can break, this may lead to falls from the bike and possible injuries e.g. fractures, bruising.

The brand is SCOTT. The type/number of models are the following;

286438 Speedster 50 (EU)

286442 Speedster 40 (CN)

286443 Speedster 50 (CN)

286472 Speedster Gravel 50 (CN)

286466 Speedster Gravel 50 (EU)

286465 Speedster Gravel 40 EQ (EU)

286437 Speedster 40 (EU)

286466 Speedster Gravel 40 EQ (CN)

286490 Contessa Speedster Gravel 35 (EU)

286493 Contessa Speedster Gravel 35 (CN)

The batch number and the bar code are unknown.

If your bicycle has a green dot under the fork bridge and/or a hole in the steerer tube, your bicycle is not affected.

There are approximately 15 affected products in the Republic of Ireland.

## What to do:

Consumers in possession of a recalled SCOTT Speedster 40 & 50 / speedster gravel 40 eq & 50 / Contessa Speedster gravel 35 should immediately stop using the bicycle, and return it to an authorized SCOTT dealer for a free replacement fork.

For additional information, please contact SCOTT at; [recall@scott-sports.com](mailto:recall@scott-sports.com) or tel: +41 264 60 19 00