



# PRODUCT RECALLS

## Specialized Bicycle Components recalls headlights and taillights

 MAY 11, 2016

Due to a potential fire and burn hazards, Specialized Bicycle Components have initiated a product recall for Specialized Flux and Stix Sport and Comp model bicycle headlights and taillights.

Approximately 200 affected lights were imported and distributed by Specialized (U.K.) Limited in Ireland.

### **What to do:**

Specialized Bicycle Components advice is that, consumers should immediately stop using these recalled headlights and taillights. Return them an authorised Specialized Bicycle retailer for a free repair for Flux model headlights, or a free replacement.