



PRODUCT RECALLS

Toyota recall of multiple vehicles

📅 APRIL 10, 2014

Toyota Ireland is carrying out a voluntary recall of various models. The affected vehicles are:

RAV4

Manufactured between Oct 2004 and Nov 2008

Airbag warning light may illuminate and in addition driver's airbag may become de-activated

3197 affected vehicles in Ireland

Hilux

Manufactured between Feb 2005 and Apr 2010

Airbag warning light may illuminate and in addition driver's airbag may become de-activated

1422 affected vehicles in Ireland

Yaris (1)

Manufactured between June 2005 and May 2010

If seat rail spring breaks, front seat(s) will not lock into adjusted position

3316 affected vehicles in Ireland

Yaris (2)

Manufactured between Sep 2005 and Feb 2009

Crack may occur in steering column bracket and column may tilt out of position

9 affected vehicles (Yaris T-Sport) in Ireland

Urban Cruiser (1)

Manufactured between Oct 2008 and May 2010

If seat rail spring breaks, front seat(s) will not lock into adjusted position

160 affected vehicles

Urban Cruiser (2)

Manufactured between Sep 2005 and Feb 2009

Crack may occur in steering column bracket and column may tilt out of position

19 affected vehicles in Ireland

What to do

Letters will be sent by Toyota Ireland to customers informing them of the recall. The letter will advise customers to contact their nearest Toyota dealer, who will arrange to do the necessary refit free of charge. If you have questions or concerns you should contact your local Toyota dealer or Toyota Ireland Customer Relations for assistance on 01-4190222.