



# PRODUCT RECALLS

## BMW recalls various models

 FEBRUARY 6, 2017

BMW Ireland is carrying out a voluntary recall of certain models of the following vehicles:

BMW 3 Series Sedan, Touring, Coupe, Convertible and M3

Model E46/4, E46/3, E46/2 and E46/C with all types of steering wheel

Production period July 1999 to December 2001

BMW 5 Series Sedan, Touring and M5

Model E39 with sports steering wheel or M sports steering wheel

Production period September 2000 to February 2002

BMW X5

Model E53 with sports steering wheel or M sports steering wheel

Production period April 2000 to January 2003

The recall is being carried out due to a potential problem with the front driver's side airbag. The driver's side airbag could deploy abnormally in a crash which could possibly lead to injury.

There are 4,978 affected vehicles in Ireland.

### **What to do:**

BMW Ireland will be writing directly to those owners involved in the recall to arrange to have their vehicles fitted with a new airbag inflator. The letter will advise you to contact your nearest BMW dealer who will arrange to do the refit free of charge. You can also contact BMW Ireland directly on 1890 719 421.