



PRODUCT RECALLS

Bosch Power Tools Voluntary Recall

📅 DECEMBER 19, 2016

Bosch Power Tools, in the course of their ongoing quality controls have determined that, due to a faulty component, the cutting or grinding disc together with the fastening fixture (spindle) could become detached during operation on a limited number of series GWS 20, GWS 22 and GWS 24 angle grinders. These models were produced from June 2016 through to August 2016. The model GWS 24-230 JVX Professional with brake is from the production period February 2016 to October 2016.

They can be clearly identified in the following ways:

1. On the tool's original packaging:

NAME	PART NO.	MANUFACTURING YEAR/MONTH (SEE PACKAGING LABEL EXPLANATION BELOW)
GWS 20	0601850L...	06, 07, 08.2016 (606,607,608)
	0601850M... 06018501...	06, 07, 08.2016 (606,607,608)
	0615990...	07-11.2016 (607,608,609,610,611)
GWS 22	0601881... 1607000...	06, 07, 08.2016 (606,607,608)
	0615990...	07-11. 2016 (607,608,609,610,611)


The first digit of the number outlined in red indicates the production year, the next two digits indicate the production month. A product with the numerical sequence 510 was therefore manufactured in October 2015 ("5" for the year 2015 and "10" for the month October). Accordingly, the number

outlined in this case indicates the manufacturing month June 2016 ("6" for the year 2016 and "06" for the month June).



2. On the type plate (found on the tool itself):

MODEL	PRODUCT NUMBER	SERIAL NUMBER
GWS 20-230 H	3601H50102 / 3601H50L01 / 3601H50L03 / 3601H50L62 / 3601H50L72 / 3601H50L73	606... - 608...
GWS 22 - 180 H	3601H81102 / 3601H81L02 / 3601H81L62 / 3601H81L72	606... - 608...
GWS 22 - 230 H	3601H82103 / 3601H82L03 / 3601H82L63 / 3601H82L73	606... - 608...



What to do:

Consumers can check online whether their angle grinder is affected on the www.anglegriercare.com website. If so, we urge them to call Bosch Power Tools as soon as possible on their customer service number 01-4666700.