



PRODUCT RECALLS

Citroen Recall C4 Picasso (B78)

 DECEMBER 6, 2017

Citroen Ireland is carrying out a voluntary recall of certain C4 Picasso (B78) vehicles.

The risk identified on affected vehicles, the bonnet skin-bonnet lining joint may prove unfit for its intended purpose.

The repair involves reinforcing this joint by adding adhesive, in order to ensure the long-term hold of the bonnet skin on the lining.. In very rare cases, the bonnet will need to be replaced. A total of 545 vehicles in Ireland are affected by this recall.

What to do

All affected consumers will be notified directly by letter by Citroen, inviting them, to contact their nearest Citroen dealer, to arrange for the necessary work to be carried out free of charge. Should consumers wish to contact Citroen directly, the Citroen customer service contact number is (01) 810 8800