



# PRODUCT RECALLS

## Hyundai Ireland Recalls passenger vehicle on i40 Models

📅 JANUARY 23, 2018

Hyundai Ireland is carrying out a voluntary recall on certain Hyundai i40 models that were produced between April 2011 and March 2012.

Hyundai has established the vehicle is fitted with an ignition lock switch that may fail to operate.

This affects 191 cars in Ireland.

### What to do

Hyundai Ireland will be writing directly to the owners of the affected vehicles to arrange to have their ignition locks replaced with a modified version. The letter will advise owners to contact their nearest authorised Hyundai service centre to have the required action completed which will be free of charge. You can also contact Hyundai Ireland customer care directly on: 01 460 9800 or email [service@hyundai.ie](mailto:service@hyundai.ie).