



PRODUCT RECALLS

Hyundai recalls certain Tuscon models

📅 JUNE 14, 2016

Hyundai Ireland is carrying out a voluntary recall of certain models of the Tuscon. The affected vehicles were manufactured between 13 April 2015 and 18 March 2016.

Hyundai have discovered that the bonnet release catch may need to be replaced on some models.

1,441 affected vehicles have been placed on the Irish market.

What to do

Hyundai Ireland will contact all affected customers by letter to arrange to have a refit carried out if necessary. If you have any questions, you can contact Hyundai Ireland on 01 460 9800