



# PRODUCT RECALLS

## Mitsubishi recalls passenger vehicle model ASX (GA0W)

📅 JANUARY 23, 2018

Mitsubishi Motors Corporation is carrying out a voluntary recall of model ASX (GA0W).

Mitsubishi has established two separate issues, impacting vehicles manufactured between 2015-2015.5 MY.

**Risk 1:** Impacting certain, effected vehicles *"...The engine ECU relay can be abnormally heated up. The engine can stall while driving and can be not able to start."* A voluntary measure has been initiated to recall vehicles from end-users: *"Return all involved vehicles to the dealer workshop to replace the engine ECU relays with the new one."*

It is estimated that 673 vehicles in the Republic of Ireland are impacted by this recall.

**Risk 2:** Impacting certain, effected vehicles *"...The door lock mechanism in the door latch might not operate properly in high temperatures...The door may not be locked sufficiently and may open itself while driving."* A voluntary measure has been initiated to recall vehicles from end-users: *"Return all involved vehicles to the dealer workshop to replace the door latches with the new one."*

It is estimated that 246 vehicles in the Republic of Ireland are impacted by this recall.

What to do:

Mitsubishi Ireland will be directly contacting effected vehicle owners to arrange to have cars brought in for necessary repair and/or replacement of parts. If you believe that your vehicle is among those effected, you can contact Mitsubishi Ireland's customer care on: **1890 41 51 61**.