



PRODUCT RECALLS

Recall notice relating to Royal Enfield Motorcycles

 SEPTEMBER 4, 2020

It has been reported that there is a serious risk relating to certain Royal Enfield Motorcycles, see list below.

Himalayan 410

Interceptor 650

Continental GT 650

The risk reported is that when motorcycles are used on roads on which a large quantity of salt has been applied during the winter for melting ice, and if brake calipers are not cleaned thereafter, corrosion of the brake callipers can occur which can cause the brakes to drag or braking performance could be affected or become ineffective.

Affected vehicles were produced between 01 October 2017 and 01 May 2020.

What to do:

If you believe that your vehicle may be impacted by this recall please contact the retailer from where you purchased the affected product.