



PRODUCT RECALLS

Suzuki Ireland recalls Ignis

 JUNE 3, 2015

Suzuki Ireland has issued a recall of its Ignis motor vehicles due to a potential smoke and fire risk at the ignition switch. The production range spans from 2000 to 2002. There are 985 vehicles affected on the Irish market.

What to do

Suzuki Ireland will contact all the owners involved in this recall and arrangements are in hand to have the affected vehicles refitted if necessary. You can contact Suzuki Ireland on 01 4145191.