



PRODUCT RECALLS

TRESemmé Philips Foldable Hairdryer recall

📅 JUNE 21, 2011

TRESemmé Philips is carrying out a voluntary recall of its Foldable Hairdryer models produced between February 2006 and November 2008.

There is a risk that the hairdryer can overheat when left plugged into the electric connection, posing a potential fire hazard even when the hairdryer is not in use.

The affected appliance has the Product Type Number HP4829.

What to do:

If you have one of the affected models **stop using it immediately** and ensure it is unplugged from the electrical socket.

Visit www.philips.ie/replace for more information or call 1800 81 88 34 to check if your appliance is affected and register for a replacement. All affected hairdryers will be replaced free of charge.