



PRODUCT RECALLS

Urgent safety warning on Grasslin QE7 water-heating timer

📅 JANUARY 13, 2012

In 2005 a fault was identified with the back plate component of Grasslin QE7 Electric water-heating timers which could cause the units to overheat and go on fire. While efforts have been made since then to replace or repair all affected units, there are still a number of affected units in the homes of consumers in Ireland which have not been replaced or repaired.



What to do:

If you have a Grasslin QE7 Electric Water-Heating Timer which was not previously replaced **stop using the device immediately**. Do not use the main switch and boost buttons while sleeping or out of the house. Please contact CJP Electrical Ltd on 0404 67689 or email qe@ge.com and they will arrange to replace your unit free of charge.