



PRODUCT RECALLS

Volvo C30, S40 and V50 model recall

 FEBRUARY 21, 2011

Volvo is recalling the following Volvo models:

C30, S40 and V50—model year 2007 vehicles

This recall is due to an issue relating to the cooling fan control module. Under certain operating conditions water intrusion may occur causing a short circuit which, in rare instances could result in a fire in the engine compartment.

The recall involves 655 vehicles in Ireland.

What to do:

Letters will be sent by Volvo to the owners of affected vehicles informing them of the recall and asking that they arrange for an appointment to have the required work completed. Consumers can also contact their nearest Volvo dealer to enquire if their vehicle is involved.

Any work carried out as part of this recall will be completed free of charge.