




# PRODUCT RECALLS

## Yeti recalls Hopper M20 (backpack); Hopper M30 2.0 (tote) and Sidekick Dry (gear case)

📅 MARCH 16, 2023

Yeti recalls Hopper M20 (backpack); Hopper M30 2.0 (tote) and Sidekick Dry (gear case).



The risk presented by these products is injuries. The magnet lined closures of certain soft backpack coolers, tote coolers and gear cases can fail and release the magnets, posing a risk of serious injury or death if the magnets are ingested.

The brand is Yeti. The type/number of models are Hopper M20 (backpack); Hopper M30 2.0 (tote) and Sidekick Dry (gear case). The barcodes are 888830070703; 888830070710; 888830070673; 888830070697; 888830063774; 888830070277; 888830070215; 888830070345; 888830134276; 888830176177; 888830190951; 888830190968; 888830210901; and 888830210727.

There are approximately 105 affected products in the Republic of Ireland.

## What to do:

Customers should stop using the product immediately. For more information on the Yeti Recall and Refund policy please see the [🔗 Yeti Product Recall page](#).