



PRODUCT RECALLS

Product Safety Information Notice on a Glen Dimplex Belling Gas Hobs Gas Supply Elbow Joint

📅 MAY 19, 2023


A safety issue has been identified with Glen Dimplex Home Appliance Ltd manufactured Belling Gas Hobs Gas Supply Elbow Joint installed in **holiday homes and caravans** manufactured after May 2019.




444410131 BEL
GHU602GC Sta



444410132 BEL
GTG60C Bk




444410193 ST
GTG60C Bk



444410444 BEL
GTG600C LPG Bk



444410134 BEL
GTG75C Bk



444411638 BEL
GHU753RI STA



444410443 BEL
GHU602C LPG
Sta



444410447 BEL
GTG75C LPG Bk



444410446 BEL
GHU75C LPG Sta



444410133 BEL
GHU75C Sta

The risk associated with the product is that of fire as the gas supply elbow joint from the gas hob to the gas supply to the property may fracture, which can cause gas to leak through the fracture and presents a serious fire risk which could pose a risk to health, or even death.

The brand is Belling. The batch numbers and the barcodes are unknown. The type of models can be viewed below:

444410131	BEL GHU602GC Sta
444410132	BEL GTG60C Blk
444410133	BEL GHU75C Sta
444410134	BEL GTG75C Blk
444410193	ST GTG60C Blk
444410443	BEL GHU602C LPG Sta
444410444	BEL GTG600C LPG Blk
444410446	BEL GHU75C LPG Sta
444410447	BEL GTG75C LPG Blk
444411638	BEL GHU753RI STA

Glen Dimplex Home Appliances limited have confirmed approximately 100 products have been sold to customers in the Republic of Ireland. An update to the number of products affected will follow.

What to do:

it is vitally important that consumers do not use their gas hob. They MUST isolate the gas supply immediately, by turning off the isolation valve to the appliance, or to the holiday home or caravan. It is vital that all Belling gas hobs detailed above, installed in a holiday caravan manufactured after May 2019, are urgently inspected and modified. This will be conducted free of charge by a Registered Gas Installer. When the important modification is carried out and certified by a Registered Gas Installer, the hob will be safe to use.

If you own one of the affected hobs, or have any concerns, please contact Belling via their email address contactus@belling.co.uk or by telephone on 01 691 7111