



PRODUCT RECALLS


Product Safety Information Notice on Belling Gas Hobs, Gas Supply Elbow Joint

📅 JULY 17, 2023


A safety issue has been identified with Glen Dimplex Home Appliances Ltd manufactured Belling Gas Hobs, Gas Supply Elbow Joints, manufactured after May 2019 and which may be installed in **domestic settings and the leisure market (holiday homes, caravans and boats)**.



444410131 BEL
GHU602GC Sta



444410132 BEL
GTG60C Blk



444410133 BEL GHU75C Sta



444410134 BEL GTG75C
Blk



444410443 BEL
GHU602C LPG Sta



444411636 BEL
GHU603CI



444410446 BEL GHU75C LPG Sta

444411637 BEL GTG603RI BLK

444411639 BEL GHU753CI



444411640 BEL GTG753RI BLK

The risk

associated with the product is that of fire as the gas supply elbow joint from the gas hob to the gas supply may fracture, which can cause gas to leak through the fracture and presents a serious fire risk which could pose a risk to health, or even death.

The brands are Belling. The batch numbers and the barcodes are unknown. The 10 models can be viewed below:

SKU NO.	SKU NAME
444410131	BEL GHU602GC Sta
444410132	BEL GTG60C Blk
444410133	BEL GHU75C Sta
444410134	BEL GTG75C Blk
444410443	BEL GHU602C LPG Sta

SKU NO.	SKU NAME
444410446	BEL GHU75C LPG Sta

444411636	BEL GHU603CI STA
444411637	BEL GTG603RI BLK
444411639	BEL GHU753CI STA
444411640	BEL GTG753RI BLK

We currently understand the number of the above product units sold to customers in the Republic of Ireland is 1850.

What to do:

It is vitally important that consumers do not use their gas hob.

The CCPC is in contact with the manufacturer to ensure that they inform consumers of this safety issue and address the risks from any affected hobs they have already supplied. We will provide an update as soon as possible.

In the meantime, if you smell gas, please contact Gas Networks Ireland immediately on 1800 20 50 50.