



# PRODUCT RECALLS

## Product Safety Information Notice on Car & Home Massage Pillow, 8028 on the Amazon Platform

📅 FEBRUARY 10, 2023

A safety issue has been identified with Car & Home Massage Pillow, 8028 sold on the Amazon Platform.



The affected products present a risk of electric shock as the plug does not meet the dimensional requirements of the relevant standard.

The unique Amazon Standard Identification Number (ASIN) is B097R4XXQS. The Barcode / SKU is X001M63X8P. The Model is KAT24W01. Another product identifier is FBA15G6BN55JU000032.

There were approximately 86 affected products in the Republic of Ireland. The affected products were sold on the Amazon platform.

## What to Do

If you purchased one of these products, please discontinue use immediately. You may wish to contact Amazon to see if there are any remedies available to you. This can be done via your user account on the Amazon platform.