



PRODUCT RECALLS

Product Safety Information Notice on Petzl ASTRO Guide Harness

📅 MAY 3, 2024

A safety issue has been identified with Petzl ASTRO Guide Harness.



The product presents a risk of injuries due to a defect on the gated opening attachment point of the harness. This could result in a life-threatening situation for the user such as a risk of death due to strangulation or falling from a height.

The brand is Petzl. Further details in relation to the affected products can be found in the table below:

PRODUCT NAME:	REFERENCES:	SERIAL NUMBER:
ASTRO BOD FAST European version	C083AA00 C083AA01 C083AA02	All serial numbers up to 23J 0000000 000 included.
ASTRO BOD FAST international	C083BA00 C083BA01	All serial numbers up to 23J 0000000 000

version	C083BA02 C083BA03 C083BA04 C083BA05	included.
ASTRO SIT FAST	C085AA00 C085AA01 C085AA02	All serial numbers up to 23J 0000000 000 included.

There are approximately 134 affected products in the Republic of Ireland.

What to do:

Customers should stop using the product immediately and inspect their harness. To check if your harness is affected by this recall, please access the Petzl safety notice [here](#).

If there is a green sticker inside your harness's plasticized label (located inside the belt), it has already been inspected and is deemed compliant and safe for consumer use.

Products with a serial number past 23J 0000000 000 will not have a green sticker inside as it is new stock with a conforming part.

Alternatively, for further guidance customers can email Petzl directly at aftersales@petzl.co.uk